



ISO Class Particle Reduction Clean

- Stage 1** Vacuum all surfaces with hepa filtered Vac.
- Stage 2** Particle roll off surfaces.
- Stage 3** Wash all surfaces with Klercide neutral detergent.
- Stage 4** Rinse all surfaces.
- Stage 5** Wipe all fittings and furniture with IPA wipes.

Equipment/Chemical List

<u>Product Name</u>	<u>Product Code</u>
Klerwipe CR IPA Tub Wipe	WPK 3900
Microfibre Flat Mophead	DM-F4OL-L
Klercide CR Biocide Y Concentrate	KCR725
Tyvek Coverall	74936

All products supplied my Guardline/Lynbond.